

INSPECTION RECORD F.A.R. 43.11-91.409

DATE AIRCRAFT TIME
IN SERVICE

SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

AVSTAR Aircraft of Washington, Inc.

Quality Aviation Maintenance

PIERCE COUNTY AIRPORT

253-770-9964

Specializing in Beechcraft and other fine High-Performance aircraft

PUYALLUP, WA 98374

www.avstarair.com

September 16, 2019 N18MD Hobbs 1807.0 Airframe. Installed new I/B exhaust, RH engine: K96-950002-57, S/N 271200; K96-950002-7, S/N 268013; K96-950002-9, S/N 268027. Replaced RH throttle position switch, flight check required. Cleaned and lubricated stall warning switch, flight check required. CWCR, checked nose gear door rigging, sat. Installed BAS shoulder harnesses in front row, see form FAA-337 & weight & balance / equipment list amendment, both this date. Operational inspection of affected systems sat.


Michael E. Thompson

A&P35177291A

INSPECTION RECORD

F.A.R. 43.11-91.409

Hillsboro Beechcraft



KH10 Hillsboro Airport

Dec 9, 2019	N18MD	Airframe	Beech D55 s/n TE-455	Hobbs 1824.4	4792.1 TTAF
-------------	-------	----------	----------------------	--------------	-------------

Removed defective Artex ELT45 and replaced with new Artex 345 serial number 317-01340 and new ELT Battery p/n A3-06-2883 serial number 382910-045 Revision E. **NEW ELT BATTERY EXPIRATION OCT 2026.** Performed ELT check, 91.207 check, and test flown, all found satisfactory. ~~~ Nothing follows. ~~~


J. Michael Brannigan, 2812174AP

ACR ELECTRONICS, Inc.
Artex Products - CAGE Code 18560
Fort Lauderdale, FL 33312
LOG BOOK ENTRY N18MD
E.L.T. BATTERY
REPLACEMENT DATE OCT, 2026